## 【道路施設の健全度の割合】

施設名	全施設数 〈R6.3時点〉	健全度(損傷の程度)			
		<b>IV(緊急措置段階)</b> II(早期措置段階) II(予防保全段階) I (健全)			
橋梁	<b>4,281</b> (100.0%)	<b>0</b> (0.0%)	<b>614</b> (14.3%)	<b>2,383</b> (55.7%)	<b>1,284</b> (30.0%)
トンネル	<b>137</b> (100.0%)	<b>0</b> (0.0%)	<b>59</b> (43.1%)	<b>72</b> (52.6%)	<b>6</b> (4.4%)
横断歩道橋	<b>67</b> (100.0%)	<b>0</b> (0.0%)	<b>35</b> (52.2%)	<b>25</b> (37.3%)	<b>7</b> (10.4%)
カルバート	<b>64</b> (100.0%)	<b>0</b> (0.0%)	<b>32</b> (50.0%)	<b>32</b> (50.0%)	<b>0</b> (0.0%)
シェッド	<b>9</b> (100.0%)	<b>0</b> (0.0%)	<b>5</b> (55.6%)	<b>4</b> (44.4%)	<b>0</b> (0.0%)
門型標識等	<b>83</b> (100.0%)	<b>0</b> (0.0%)	<b>17</b> (20.5%)	<b>55</b> (66.3%)	<b>11</b> (13.3%)

<sup>※</sup>令和5年度定期点検の結果を反映